

PredictWind 2024 International Moth Class World Championships

Equipment Substitution Request

Received: 2025-01-07 09:12 NZDT

Request No: 16

Boat: Moth - AUS 5055 - Scott Babbage

Request:

Old Equipment:

MH-V5

New Equipment:

MH-V5

Reason:

My front horizontal MH-V5 has failed at the flap hinge. The manufacturer Mackay Boats has confirmed the failure and wants to replace the foil with a like for like MH-V5. This failure is unforeseeable and at no fault of my own.

Response: Approved

It will be approved on condition that the broken foil is shown to Allan Punch, Richard Didham, Sam Barnet or Graeme Sutherland for inspection but not one of those from your Country Then see Measurer Shaun Ritson for the sticker

Response By Harold Bennett Printed at 2025-05-05 07:43
NZST