



Wayfarer National Champions

Equipment Substitution Request

Received: 2023-07-01 18:49 UTC

Request No: 02

Boat: Wayfarer - 11093 - Restless - Andrew Wilson

Request:

Old Equipment:

Mast

New Equipment:

Mast, borrowed from Tim Wood.

Reason:

Jib halyard sheeve has failed, preventing jib halyard movement (eg raise or lower jib). No replacement sheeves available at chandlery, so easiest to borrow complete mast.

The masts are similar (one design).

Response: Approved

*Response By Paul Jackson Printed at 2025-05-14 03:19
UTC*