



41 Copa del Rey MAPFRE

Question for Officials

Date: 2023-08-03

Question No: 03

Question For: Technical Committee

Question:

TEAM EARLYBIRD has a total engine break down after overheating - they will have no engine to get in out or moor the boat

We request to have Tom Swift (Boat Captain) driving the Earlybird rib and have him to tow us in and out

Please confirm

Answer:

Allow to tow the boat, following appendix H of class rules, no crew changes , no sails on board the rib

Response By Antonio Cardona Printed at 2025-05-10 20:33