Sail India 2021

Equipment Substitution Request

Received: 2021-12-13 05:30 IST

Request No: 05

Boat: 470 - INDIA IND 8 - PRABHAKAR PRAVEEN

Request:

Old Equipment: Hull

New Equipment: Hull

Reason:

My trolley broke during the launch and damaged the hull. So the hull needs to be repaired.

Response: Approved

Damage physically inspected before repair and after repair . Found totally satisfied

Response By Vishnu Chandrabose Printed at 2025-05-07 01:44 IST