



2023 Formula Kite Europe Championships

Equipment Substitution Request

Received: 2023-09-22 17:03 BST

Request No: 10

Boat: Formula Kite - Men - 33 - Kent Faßbender

Request:

Old Equipment:

Nr 10558056 Frontwing Foil : Damage By Wood in The Water. I want to take it at home to repair it

New Equipment:

Permission granted to be taken out of the venue for repair. Tomorrow morning must see it.

Reason:

Foil Need to be repaired at home

Response: Approved

Repaired

*Response By Panos Mavrogeorgis Printed at 2025-05-10 12:31
BST*