



Tasar World Championships 2026 in Kunigami

Equipment Substitution Request

Received: 2026-06-06 14:36 JST

Request No: 05

Boat: Tasar - N - 2999 - Yusaku Akiyoshi

Request:

Old Equipment:

The size of the crack is around 5mm.

New Equipment:

Putting some gel cote on the crack.

Reason:

There is a very small crack at the ladder.



[IMG_9113.jpeg 1.73 MB](#)

Response: Approved
Repairs are permitted